Work Orde Thursday, June									•			Page 1
Item ID: Revision ID:	D3913-9			Accept					Setup	Start		
Item Name:	Hinge Rib									Stop		
Start Date: Required Date: Reference:	6/10/2010 6/17/2010	Start Qty: 3.00 Req'd Qty: 3.00			Cust Item II Customer:	<b>)</b> :						
Approvals:	Process Plan	n:	Date: 16-6-10		Da			]	Run	Start Stop		
	QC:		Date:	SPC (Y/N):	Da	te:				. •		
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Tool ID	Tool#		Accept Qty	Rejo Qty		Reject Tumber	Insp. Stamp
Draw Nbr	Revi	sion Nbr										
D3913	Α											•
100 Large Fab		Memo	1	0.00			(	3				
Large Fab		1- Cut tub	e as per dwg D3913 identification marks and debu	π · SA 10	1D -06-15							
110 			pleteness to step on W/O	0.00			(					
Quality Control		Memo	às	0.00	ر ب							

120

Packaging

Identify as per dwg & Stock Location: W18

Packaging

Memo

Part No:PAR #:Fault Category:NCR: Yes No DQA:Date:	proval
Resolution:	
Resolution:	
Resolution:	
Resolution:	-00-1
Resolution:	
NCR: WORK ORDER NON-CONFORMANCE (NCR)  DATE STEP Description of NC Corrective Action Section B Verification Approval App	
DATE STEP Description of NC   Corrective Action   Section B   Verification   Approval   Approval   Approval   Chief Fing   OC	
DATE STEP Description of NC Initial Action Description Sign & Verification Approval	
Section A   Initial   Action Description   Sign &   Section C   Chief Fing   QC	oroval
	nspector

#### Work Order ID 59731

Thursday, June 10, 2010 9:57:48 AM



Page 2

Item ID:

D3913-9

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Required Date: 6/17/2010

Hinge Rib 6/10/2010

Start Qty: 3.00

Req'd Qty: 3.00



**Cust Item ID: Customer:** 

Reference:

**Start Date:** 

		_
App	rova	ls:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:\_

SPC (Y/N):

Date:

Stop



Sequence ID/ **Work Center ID** 

Operation Description

Set Up/ **Run Hours** 

Tool ID

Tool # Plan

Code

Reject Accept Qty

Reject Number

Insp. Stamp

130

QC

QC21- Final Inspection - Work Order Release

0.00

Qty

Quality Control

Memo

0.00

10/06/16 Py MF 10-6-15

Dart	Aero	space	Ltd
------	------	-------	-----

W/O:			W	ORK ORDER CHANG	ES		*			
DATE	STEP	PROC	CEDURE CH	ANGE	В	у	Date C	ty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	ļ									
			•							
Part No	:	PAR #:	Fault Cat	egory:	_ NCR:	Yes N	o DQA: _		Date:	
	R	esolution:	_ Dispositi	on:	_ QA: N	C Clos	sed:		Date:	
NCR:		W	ORK ORE	DER NON-CONFORMA	ANCE (I	NCR)		-1		
DATE	STEP	Description of NC			ion B		Verificati	on	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section C		Chief Eng	QC Inspector
,	*									
									į	

#### **Picklist Print**

Thursday, June 10, 2010 9:57:52 AM

Work Order ID: 59731

Parent Item:

D3913-9

Parent Item Name: Hinge Rib

**Comments:** 

IPP Rev:A new issue DD 10.03.19 verified by:EC

**Start Date:** 6/10/2010

Required Date: 6/17/2010

10-06-15

Page 1

Start Qty: 3.00

Required Qty: 3.00


									- 0				-
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304TS0.750W.049		Purchased	No			100	f	315.5414	7.875	24.86842			

304 SQ Tube .75x.75x.049W


Location	Loc Oty	Loc Code	
MAT	315.5413419		
113763	0		
114323	29.3546289		
114677	27.30236		-
114835	258.884353		24.
MAT017	3.68448E-05		
114298	3 6845E-05		

SAD


W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					:					
			· · · · · · · · · · · · · · · · · · ·							
Part No	·	PAR #:	Fault Cate	gory:	NCR	: Yes	No <b>DQ</b> /	\.	Date:	
		olution:								
NCR:				ER NON-CONFORM						
DATE STEP		Description of NC	Corrective Action Section				Verific	ation	Approval	Approval
	0,2,	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
	:									
	Ĭ									




W/O:			W	ORK ORDER CHAN	GES				
DATE	STEP	PRO	OCEDURE CHA	ANGE	By Date				
					,				
Part No		PAR #:							
	Res	solution:	Disposition	on:	QA: N/C	Closed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	IANCE (NO	CR)			
DATE STEP		Description of NC	Initial	····	Section B ption Sign &		cation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Da		tion C	Chief Eng	QC Inspector
									1




	•									
W/O:			WO	RK ORDER CHANG	SES	<del>, ,,</del> ,	12			
DATE	STEP	PR	OCEDURE CHAI	NGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-				
Part No		PAR #:								
	Resc	olution:							Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	ICR)				
DATE	STEP	Description of NC			Section B on Sign &		Verific		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Secti	on C	Chief Eng	QC Inspector




W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	Date:	1
	Re	solution:	Disposition	on:	_ QA: N/C	Closed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NC	R)	-		
DATE	STEP	Description of NC		Corrective Action Secti		Verifi	cation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description  Chief Eng	Sign Dat	& Sec	tion C	Chief Eng	QC Inspector
								<u> </u>	
			1					ŀ	ľ



		S				
DATE STEP PROCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No: PAR #: Fault Cate	gory:	NCR: Yes	No DQA	\:	Date:	
Resolution: Disposition						
NCR: WORK ORDE	ER NON-CONFORMA	NCE (NCF	l)	<u> </u>		
DATE CTED DESCRIPTION OF NC		Verificatio		ation	Approval	Approval
Section A Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section		Chief Eng	QC Inspector
	-					
			,	:	·	



W/O:		WORK ORDER CHANGES											
DATE STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
<del></del>			-										
Part No	•	PΔR #·	Fault Cate	Jory:	NCB	y Vos	No. DOA		Dota				
. 4.1.10					NCR: Yes No DQA: QA: N/C Closed:								
NCR:				ER NON-CONFOR									
DATE	STEP	Description of NC Section A	Corrective Action Section Initial Action Description Chief Eng Chief Eng			Sign & Date	Verification Section C		Approval Chief Eng	Approval QC Inspector			
			Office Eng	Chief Eng		Date							
•				777									
İ					:								
					i i								



**D3913-15 WIDE HANDLE PLATE** 

wlo 5973/

DESIGN DART AEROSPACE LTD JHH DRAWN HAWKESBURY, ONTARIO, CANADA CHECKED DRAWING NO. REV. A D3913 MFG. APPR. SHEET 6 OF 6 APPROVED TITLE SCALE LONG BASKET BASE ASSY (350) NTS DE APPR. COPYRIGHT © 2010 BY DART AEROSPACE LTD
THIS COCUMENT IS PRIVATE AND CONTRIBUTION AND IS SUPPLED ON THE EXPRESS CONDITION OF TO BE USED FOR ANY PURPOSE OR COPED OR COMMUNICATED TO MAY OTHER PERSON. DATE 10.03.16

NOTES:
1) MATERIAL: 304/316 STAINLESS STEEL SHEET ANNEALED 2B FINISH, PER MIL-S-5059 OR AMS 5513/5524 OR ASTM A240 OR ASME SA240 REF DART SPEC M304S11GA
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 0.31 lbs

8

D

С

В

3

	•										
W/O:		WORK ORDER CHANGES							· · · · · · · · · · · · · · · · · · ·		
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							• •		· .		
					-		40.00		1-74		
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes No DQA:				Date:		
	Re	solution:							Date: _	· · · · · · · · · · · · · · · · · · ·	
NCR:		V	VORK ORD	ER NON-CONFORMA	ANCE	(NCR)					
DATE	STEP	Description of NC Section A	Initial Action Description			Sign &	Verification Section C		Approval Chief Eng	Approval QC Inspector	
			Chief Eng	Chief Eng		Date	000				
		•						•			
		· . ·							ė.		
					,						